Abstract`

5

A method for ascertaining the control voltage of a piezoelectric element is characterized by the fact that the voltage drop at the piezoelectric element following a charge process is measured and the control voltage of the piezoelectric element is inferred from this voltage drop.